

THIS IS NOT AN

INVOICE

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 11084-52-4723 State Number 22268

6

EQUIPMENT INSPECTED					
State Number: 22268	Type of Unit: Passer		Floor to Floor: 1 to 3		
Capacity: 2500 Manuf: KON			Speed: 100		
Landings: 3 Installed: 03		4	Rope Size: 0		
Volts: 208	Complied: 03/16/20	04	Entrances: 1		
OWNER		OCCUPANT			
NORTHWESTERN REGIONAL HOUSING		ELK PARK APARTMENTS			
P.O. BOX 2510		256 ELK PARK SCHOOL ROAD			
BOONE, NC, 28607		ELK PARK, NC, 28622			
	INSPEC	CTION INFORMATION			
Inspection Date 03/25/2011	Type Inspection Routine	Certificate Status Re-issued	Inspector 52 - Sosebee	County AVERY	
		VIOLATIONS			
	ncy telephone in proper working order. ne car emergency light and alarm bell ir		ork when 110 power is off.)		
			ork when 110 power is off.)		
	ne car emergency light and alarm bell in		ork when 110 power is off.)		
Resteps to place the steps to place the step the step to place the step to place the step to place the step the step to place the step the step the step the step the	ne car emergency light and alarm bell in	n proper working order.(Neither w		equipment into	

P.O. BOX 2510 BOONE, NC, 28607

NORTHWESTERN REGIONAL HOUSING

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to: