



INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
11118-17-5029
State Number
26812

EQUIPMENT INSPECTED

State Number: 26812	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2100	Manuf: SCHINDLER	Speed: 100
Landings: 2	Installed: 06/09/2009	Rope Size:
Volts: 208	Complied: 06/09/2009	Entrances: 1
OWNER	OCCUPANT	
ARDEN SEVENTH DAY ADVENTIST CHURCH	ARDEN SEVENTH DAY ADVENTIST CHURCH	
35 AIRPORT ROAD	35 AIRPORT ROAD	
ARDEN, NC, 28704	ARDEN, NC, 28704	

INSPECTION INFORMATION

Inspection Date 04/28/2011	Type Inspection Routine	Certificate Status Re-issued	Inspector 17 - White	County BUNCOMBE	11 A
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------	------

VIOLATIONS

- 8.11.3.2.1 Provide the annual relief valve and system pressure test.
- 2.27.1.1.2 Put the in car emergency telephone in proper working order.
- 8.6.10.1 Perform a monthly firefighters Phase 1 and 2 test with the key switches and a minimum one floor run. Document test results with availability to inspector.
- 2.2.5.1 Put the pit lights in proper working order.
- 8.6.4 Provide the proper operation of the oil warming operation/ unit comes on and off without shutting off.

Items must be corrected by: 05/28/2011

Elevator Name: 1

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: office

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ARDEN SEVENTH DAY ADVENTIST CHURCH
35 AIRPORT ROAD
ARDEN, NC, 28704