



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
11137-52-4146
State Number
25868

EQUIPMENT INSPECTED

State Number: 25868	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2500	Manuf: OTIS	Speed: 100
Landings: 2	Installed: 03/27/2008	Rope Size: 0
Volts: 480	Complied:	Entrances: 1
OWNER	OCCUPANT	
YMCA OF AVERY COUNTY	YMCA OF AVERY COUNTY	
436 HOSPITAL DRIVE	436 HOSPITAL DRIVE	
LINVILLE, NC, 28646	LINVILLE, NC, 28646	

INSPECTION INFORMATION

Inspection Date 05/17/2011	Type Inspection Routine	Certificate Status Re-issued	Inspector 52 - Sosebee	County AVERY
-------------------------------	----------------------------	---------------------------------	---------------------------	-----------------

6

VIOLATIONS

8.6.4.7.4	Remove the oil from the pit floor. Oil in sump hole.
8.6.1.6	General Maintenance Methods and Procedures. Tighten loose in car handrails.
8.11.3.2.1	Perform the annual relief valve and system pressure test and provide proper tag.

Items must be corrected by: 06/16/2011

Elevator Name: # 3

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Dennis Henson 828-737-7588

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

YMCA OF AVERY COUNTY
436 HOSPITAL DRIVE
LINVILLE, NC, 28646