



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
11153-48-0830
State Number
H2067

EQUIPMENT INSPECTED

State Number: H2067	Type of Unit: Hand Lift	Floor to Floor: 1 to 2
Capacity: 750	Manuf: SAVARIA	Speed: 15
Landings: 2	Installed: 01/27/2009	Rope Size:
Volts: 110	Complied: 01/27/2009	Entrances: 2
OWNER	OCCUPANT	
MT OLIVE BAPTIST CHURCH	MT OLIVE BAPTIST CHURCH	
2919 GALLOWAYROAD	2919 GALLOWAYROAD	
BOLIVIA, NC, 28422	BOLIVIA, NC, 28422	

INSPECTION INFORMATION

Inspection Date 06/02/2011	Type Inspection Routine	Certificate Status Not Issued	Inspector 48 - Martin	County BRUNSWICK
-------------------------------	----------------------------	----------------------------------	--------------------------	---------------------

10

VIOLATIONS

N/A Partial insp. - unit runs 4" out of floor and stops. [repair] Certificate not issued

Items must be corrected by: 07/02/2011

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: UNAVAILABLE

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

MT OLIVE BAPTIST CHURCH
2919 GALLOWAYROAD
BOLIVIA, NC, 28422