



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
11159-16-2785
State Number
17645

EQUIPMENT INSPECTED

State Number: **17645**

Capacity: 2100

Landings: 3

Volts: 208

Type of Unit: Passenger

Manuf: THYSSEN KRUPP

Installed: 11/02/1998

Complied: 03/10/2005

Floor to Floor: 1 to 3

Speed: 100

Rope Size: 0

Entrances: 1

OWNER

WYNNE VIEW INC

PO BOX 115

BELHAVEN, NC, 27810

OCCUPANT

WYNN VIEW OFFICE BLDG

104 W WATER ST

BELHAVEN, NC, 27810

INSPECTION INFORMATION

Inspection Date
06/08/2011

Type Inspection
Routine

Certificate Status
Re-issued

Inspector
16 - Moore

County
BEAUFORT

7

VIOLATIONS

8.6.4.15 Take steps to place the car emergency light in proper working order.

Items must be corrected by: 07/08/2011

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Linda Phillips

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

WYNNE VIEW INC
PO BOX 115
BELHAVEN, NC, 27810