

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 11159-36-4251 State Number 27887

1

	E	QUIPMENT INSPECTED			
State Number: 27887	Type of Unit: Passenger		Floor to Floor: 1	Floor to Floor: 1 to 4	
Capacity: 4500	Manuf: SCHINDLER		Speed: 100	Speed: 100	
Landings: 4	Installed: 06/08/2011		Rope Size:		
Volts: 208	Complied: 06/08/2011		Entrances: 2		
OWNER	OCCUPANT				
FIRST BAPTIST CHURCH	FIRST BAPTIST CHURCH OF BURLINGTON				
400 S BROAD STREET	400 S B	400 S BROAD STREET			
BURLINGTON, NC, 27215	BURLIN	NGTON, NC, 27215			
	INS	PECTION INFORMATION			
Inspection Date 06/08/2011	Type Inspection New	Certificate Status Issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
complainace with current codes. Violations pointed out to: Ray E.	ing on Corrected Violations Form w	, and the second	Inspector	ng your equipment into	
	To make changes to the invoice mai	iling address please call: 919-7.	33-0372		
THIS IS NOT AN	An invoice will be mailed to:	FIRST BAPTIST CHUR 400 S BROAD STREET BURLINGTON, NC, 27:	СН		