NCDOL NCDOL NA Department of later

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 11161-48-4650 State Number 27879

	EQU	UIPMENT INSPECTED			
State Number: 27879	Type of Unit: Pass	Type of Unit: Passenger Manuf: TKE		1 to 2	
Capacity: 2500					
	andings: 2 Installed: 06/10/2011		Speed: 125 Rope Size: Entrances: 1		
Volts: 208					
OWNER	1	OCCUPANT			
FIRST BANK		FIRST BANK BUILDING - SHALLOTTE			
10 WATERFORD BUS CTR WA	V				
BELVILLE, NC, 28451	.1				
	INSPE	ECTION INFORMATION			
Inspection Date 06/10/2011	Type Inspection New	Certificate Status Issued	Inspector 48 - Martin	County BRUNSWICK	
		VIOLATIONS			
Elevator Name: # 1					
Notify the Elevator Bureau in writin complainace with current codes.	g on Corrected Violations Form who	en the following corrections	have been made in order to	bring your equipment into	
Violations pointed out to: GARY [7			Inspector		
T	To make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN INVOICE A	FIRST BANK An invoice will be mailed to: 10 WATERFORD BUS CTR WAY BELVILLE, NC. 28451				