

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 11172-36-134 State Number H85

1

	E	EQUIPMENT INSPECTED			
State Number: H85	Type of Unit: Hand L	Floor to Floor:	Floor to Floor: 1 to 2		
Capacity: 400	Manuf: AMER STAIR GLID		Speed: 9		
Landings: 2	Installed: 01/17/1983		Rope Size:	Rope Size:	
Volts: 110	Complied: 01/17/1983		Entrances: 2		
OWNER		OCCUPANT			
NEW BIRTH BAPTIST CHURCH]	NEW BIRTH BAPTIST CHURCH			
424 S FLANNER ST		424 S FLANNER ST			
BURLINGTON, NC, 27215		BURLINGTON, NC, 27215			
	IN	SPECTION INFORMATION			
Inspection Date 06/21/2011	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
None found					
Notify the Elevator Bureau in writing omplainace with current codes.	g on Corrected Violations Form	when the following corrections	have been made in order to bri	ng your equipment into	
/iolations pointed out to: Mrs. Vanh	nook 336-452-0987				
То	make changes to the invoice ma				
THIS IS NOT AN INVOICE An	invoice will be mailed to:	NEW BIRTH BAPTIST 424 S FLANNER ST BURLINGTON NC 27			