NCDOL NCDOL

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 11173-48-3716 State Number H1874

	E	QUIPMENT INSPECTED			
State Number: H1874 Capacity: 750 Landings: 2 Volts: 120	Type of Unit: Hand Lift Manuf: GARAVENTA Installed: 04/10/2008 Complied: 04/10/2008		Floor to Floor: 1 to 2 Speed: 17 Rope Size: Entrances: 1		
	complica. on	OCCUPANT	Entrances. 1		
OWNER BEACH MANAGEMENT		PENINSULA CLUBHOUSE			
PO BOX 6569		44 PENINSULA			
OCEAN ISLE BEACH, NC, 28469		OCEAN ISLE BEACH, NC, 28469			
	INS	SPECTION INFORMATION			
Inspection Date 06/22/2011	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	
		VIOLATIONS			
N/A ROUGH RID					
Items must be corrected by: 07/Notify the Elevator Bureau in writin complainace with current codes. Violations pointed out to: WANDA	ng on Corrected Violations Form v	when the following corrections	_	bring your equipment into	
	To make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN INVOICE	an invoice will be mailed to:	BEACH MANAGEMEN PO BOX 6569 OCEAN ISLE BEACH,			