

THIS IS NOT AN

INVOICE

An invoice will be mailed to:

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 11199-52-0678 State Number 8962

6

		EQ	UIPMENT INSPECTED		
State Number: <b>8962</b> Capacity: 2000 Landings: 2 Volts: 220 OWNER ESEECOLA LODGE P.O BOX 99 LINVILLE, NC, 28646		Type of Unit: Passenger  Manuf: THYSSEN KRUPP Installed: 06/02/1977 Complied: 06/02/1977  OCCUPANT ESEECOLA LODGE CLUBHOUSE 83 ROSEBORO ROAD LINVILLE, NC, 28646		Floor to Floor: 1 to 2 Speed: 100 Rope Size: 0 Entrances: 1	
				2	
		INSP	ECTION INFORMATION		
Inspection Date 07/18/2011		Type Inspection Routine	Certificate Status Re-issued	Inspector 52 - Sosebee	County AVERY
			VIOLATIONS		
2.27.1.1.2		nergency telephone in proper workin			
2.27.1.1.2 8.11.3.2.1 NEC NEC	Provide the annu All wiring must	nergency telephone in proper working ual relief valve and system pressure to be in electrical conduit or boxes, in cover on electrical box in machine ro	est, and provide proper tag. machine room.		
8.11.3.2.1 NEC NEC	Provide the annu All wiring must	ual relief valve and system pressure to be in electrical conduit or boxes, in sover on electrical box in machine round to the system of the sy	est, and provide proper tag. machine room.		
8.11.3.2.1 NEC NEC	Provide the annual All wiring must Install missing control of the corrected by: 08/tor Bureau in writing	ual relief valve and system pressure to be in electrical conduit or boxes, in sover on electrical box in machine round to the system of the sy	est, and provide proper tag. machine room. om.	een made in order to bring your	equipment into

P.O BOX 99 LINVILLE, NC, 28646

ESEECOLA LODGE