N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
11207-8-0076
State Number
2050

EQUIPMENT INSPECTED

State Number: **2050**
Capacity: 1500
Landings: 2
Volts: 220

Type of Unit: Freight
Manuf: ROTARY
Installed: 04/03/1953
Complied: 04/03/1989

Floor to Floor: B to 2
Speed: 50
Rope Size:
Entrances: 2

OWNER
ANSON CO ADMIN BLDG
101 S.GRENE ST
WADESBORO, NC, 28170

OCCUPANT
ANSON CO ADMIN BLDG
101 S.GREENE ST ROOM 30
WADESBORO, NC, 28170

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County
07/26/2011	Routine	Re-issued	8 - Burris	ANSON

4

VIOLATIONS

8.6 REMOVE WATER FROM PIT
8.6 RESTORE OPERATION OF PIT SUMP PUMP

Elevator Name: SIDEWALK ELEV

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: REP- WENDELL WILLIAMSON

Inspector _____

THIS IS NOT AN INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:
ANSON CO ADMIN BLDG
101 S.GRENE ST
WADESBORO, NC, 28170