NCDOL NCDOL NA Department of John

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 11210-8-2488 State Number 17537

76

	E	QUIPMENT INSPECTED			
State Number: 17537	Type of Unit: Passenger		Floor to Floo	Floor to Floor: 1 to 3	
Capacity: 2500	Manuf: THYSSEN	Manuf: THYSSEN KRUPP		Speed: 100	
Landings: 3	Installed: 06/22/19	Installed: 06/22/1998		Rope Size:	
/olts: 208	Complied: 05/27/2	Complied: 05/27/2003		Entrances: 1	
OWNER		OCCUPANT			
CASPN ELDERLY HOUSING		CASPN ELDERLY HOUSING			
PO BOX 609		945 S CHURCH ST			
ASHEBORO, NC, 27204-0609		ASHEBORO, NC, 27203			
	INS	PECTION INFORMATION			
Inspection Date 07/29/2011	Type Inspection Not Inspected	Certificate Status Not Issued	Inspector 8 - Burris	County RANDOLPH	
		VIOLATIONS			
otify the Elevator Bureau in writing	ng on Corrected Violations Form w	hen the following corrections have	ve been made in order to	bring your equipment into	
iolations pointed out to: REP					
	o make changes to the invoice ma	iling address please call: 919-733-			
THIS IS NOT AN INVOICE	An invoice will be mailed to:	CASPN ELDERLY HOUS PO BOX 609 ASHEBORO, NC, 27204-0			