

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-807-2770

Report Number 11230-36-3880 State Number 2153
--

EQUIPMENT INSPECTED

State Number: 2153	Type of Unit: Freight	Floor to Floor: 1 to 3
Capacity: 4000	Manuf: MONARCH	Speed: 60
Landings: 3	Installed: 07/22/1953	Rope Size:
Volts: 550	Complied: 07/22/1953	Entrances: 2
OWNER		OCCUPANT
INTERNATIONAL TEXTILE GROUP, INC.		BURLINGTON FINISHING
906 ANTHONY ST		906 ANTHONY ST
BURLINGTON, NC, 27215		BURLINGTON, NC, 27215

INSPECTION INFORMATION

Inspection Date 08/18/2011	Type Inspection Not Inspected	Certificate Status Not Issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------------	----------------------------------	---------------------------	--------------------

1

VIOLATIONS

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: office

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

INTERNATIONAL TEXTILE GROUP, INC.
906 ANTHONY ST
BURLINGTON, NC, 27215