NCDOL NCDOL N. Department of labor

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 11251-48-0978 State Number 24929

			EQUIPMENT INSPECTED			
State Number:	ımber: 24929 Type of Unit: Passenger			Floor to Floor: 1 to 3		
Capacity: 2500	2500 Manuf: THYSSEN KRUPP			Speed: 100		
Landings: 3		Installed: 05/30	/2007	Rope Size:		
Volts: 208		Complied: 05/3	0/2007	Entrances: 1		
OWNER			OCCUPA	OCCUPANT		
BALD HEAD	ISLAND CONST	TRUCTION, INC	BALD HE	BALD HEAD ISLAND DORM/RETAIL		
4 MARITIME WAY			10 MARIT	10 MARITIME WAY		
BALD HEAD ISLAND, NC, 28461			BALD HEAD ISLAND, NC, 28461			
		I	NSPECTION INFORMATION			
Inspection Date 09/08/2011		Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	
			VIOLATIONS			
	General Maintenance Methods and Procedures REPAIR BROKEN BUTTON ON CAR CONTROL PANEL.					
	Put the Phase I fire service feature in proper working order. Provide a class "ABC" fire extinguisher in the machine room or control space convenient to the access door.					
8.0.1.0.3 PIC	ovide a class Ab	C The extinguisher in the machin	ne room or control space convents	ent to the access door.		

Items must be corrected by: 10/08/2011

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: RICHARD SCEARCE Inspector _____

To make changes to the invoice mailing address please call: 919-733-0372

THIS IS NOT AN INVOICE

BALD HEAD ISLAND CONSTRUCTION, INC

An invoice will be mailed to: 4 MARITIME WAY

BALD HEAD ISLAND, NC, 28461