



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

### INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**11279-24-3018**  
State Number  
**27268**

### EQUIPMENT INSPECTED

|                            |                         |                        |
|----------------------------|-------------------------|------------------------|
| State Number: <b>27268</b> | Type of Unit: Passenger | Floor to Floor: 1 to 4 |
| Capacity: 2500             | Manuf: THYSSEN KRUPP    | Speed: 125             |
| Landings: 4                | Installed: 11/24/2009   | Rope Size:             |
| Volts: 240                 | Complied:               | Entrances: 2           |
| OWNER                      | OCCUPANT                |                        |
| 18 CHURCH STREET LLC       | ALTAMONT THEATER        |                        |
| 27 FOREST ROAD             | 18 CHURCH STREET        |                        |
| ASHEVILLE, NC, 28803       | ASHEVILLE, NC, 28801    |                        |

### INSPECTION INFORMATION

|                               |                            |                                 |                         |                    |      |
|-------------------------------|----------------------------|---------------------------------|-------------------------|--------------------|------|
| Inspection Date<br>10/06/2011 | Type Inspection<br>Routine | Certificate Status<br>Re-issued | Inspector<br>24 - Moore | County<br>BUNCOMBE | 11 B |
|-------------------------------|----------------------------|---------------------------------|-------------------------|--------------------|------|

### VIOLATIONS

- 8.6.4.14 Hoist way access switches, where provided, shall be maintained. Provide proper operation of both access switches top and bottom. Bottom works half/ top don't work.
- 2.27.1.1.2 Put the in car emergency telephone in proper working order.
- 8.6.4.13.1[I] Properly maintain door restrictors, where required. Rear door
- 8.6.4.13.1[c] Properly maintain door reopening devices front car door open button doesn't work with door completely closed. Rear O.K..
- 2.7.5.1 Put the machine room lights in working order. No timers on light switch.
- 8.11.1.6 Tag and seal the rupture valve in pit.

Items must be corrected by: 11/05/2011

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Brian Lee / 828-989-2924

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

18 CHURCH STREET LLC  
27 FOREST ROAD  
ASHEVILLE, NC, 28803