

Violations pointed out to: UNAVAILABLE

THIS IS NOT AN

INVOICE

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 11297-48-4679 State Number 24165

EQUIPMENT INSPECTED					
State Number: 24165	apacity: 2500 Manuf: SCHINDLER, HYD andings: 4 Installed: 02/28/2007		Floor to Floor: 1 to 4 Speed: 125 Rope Size: Entrances: 1		
Capacity: 2500					
Landings: 4					
Volts: 208					
OWNER		OCCUPANT			
THE PRESERVE C/O CAMS	S	THE PRESERVE BL	D #3 - CAR #1		
1630 MILITARY CUTOFF RD.		3100 MARSH GROVE LANE			
WILMINGTON, NC, 28403		OAK ISLAND, NC, 24465			
		NSPECTION INFORMATION			
Inspection Date 10/24/2011	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	10
		VIOLATIONS			
2.2.2.4	Install the cover on the sump pum	p.			
8.6.4.7.4	Remove the water from the pit flo	or.			
Items must be corrected by	: 11/13/2011				
	riting on Corrected Violations For	m when the following corrections	have been made in order to	bring your equipment into	

THE PRESERVE C/O CAMS

WILMINGTON, NC, 28403

1630 MILITARY CUTOFF RD.

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

Inspector ___