

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 11298-16-3129 State Number 27796

	Е	QUIPMENT INSPECTED		
State Number: 27796 Capacity: 2100 Landings: 2 Volts: 208 Type of Unit: 1 Manuf: SCHIN Installed: Complied:			Floor to Floor: 1 t Speed: 100 Rope Size: Entrances: 2	o 2
OWNER	o simplified.	OCCUPANT	Zimanioosi Z	
FIRST BAPTIST CHURCH		FIRST BAPTIST CHURCH		
113 N HARVEY STREET		113 N HARVEY STREET		
WASHINGTON, NC, 27889		WASHINGTON, NC, 27889		
	INS	PECTION INFORMATION		
Inspection Date 10/25/2011	Type Inspection New	Certificate Status Issued	Inspector 16 - Moore	County BEAUFORT
		VIOLATIONS		
n/a No viol	ations found			
Notify the Elevator Bureau in v	vriting on Corrected Violations Form v	when the following corrections have	been made in order to brir	g your equipment into
complainace with current codes. Violations pointed out to: Jim with Schindler			Inspector	
1				
THIS IS NOT AN	To make changes to the invoice mailing address please call: 919-733-0372			
INVOICE	An invoice will be mailed to:	FIRST BAPTIST CHURCH 113 N HARVEY STREET WASHINGTON, NC, 27889		