

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
www.nclabor.com/elevator.htm  
919-807-2770

Report Number <b>11298-8-2465</b> State Number <b>1167</b>
---

EQUIPMENT INSPECTED

State Number: <b>1167</b>	Type of Unit: Freight	Floor to Floor: 1 to 2
Capacity: 2000	Manuf: OTIS	Speed: 75
Landings: 2	Installed: 10/11/1948	Rope Size: 1/2
Volts: 220	Complied: 10/11/1948	Entrances: 1
OWNER	OCCUPANT	
ACME MCCRARY CORP	ACME MCCRARY CORP	
BOX 1287	159 NORTH ST	
ASHEBORO, NC, 27204-1287	ASHEBORO, NC, 27203	

INSPECTION INFORMATION

Inspection Date 10/25/2011	Type Inspection Routine	Certificate Status Re-issued	Inspector 8 - Burris	County RANDOLPH	76
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------	----

VIOLATIONS

8.6 RESTORE OPERATION OF ELEVATOR PIT SUMP PUMP. REMOVE WATER FROM PIT

Items must be corrected by: 11/24/2011

Elevator Name: Plant 3

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: REP- MARILYN VAN HORN

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ACME MCCRARY CORP  
BOX 1287  
ASHEBORO, NC, 27204-1287