NCDOL NC. Department of Labor

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 11319-48-3657 State Number 11693

		EQUIPMENT INSPECTED		
State Number: 11693 Type of Unit: Passe		Passenger	Floor to Floor: G to 3	
Capacity: 2000	Manuf: KON		Speed: 125	
Landings: 4	Installed: 02/19/1987 Complied: 02/19/1987 OCCUPANT		Rope Size: . Entrances: 4	
Volts: 0				
OWNER				
WEST BEACH VILLA	WEST BEACH VILLA			
2714 W BEACH DRIVE	714 W BEACH DRIVE 2714 W. BEACH DRIVE			
LONG BEACH, NC, 28461		LONG BEACH,	NC, 28461	
]	INSPECTION INFORMATION		
Inspection Date 11/15/2011	Type Inspection Routine	Certificate Status Not Issued	Inspector 48 - Martin	County BRUNSWICK
		VIOLATIONS		
Towns were the comment of the second	12/05/2011			
Items must be corrected by: 1		m when the following corrections	haya haan mada in ardar ta	hring your againment into
complainace with current codes.	iting on Corrected Violations For	m when the following corrections	have been made in order to	bring your equipment into
Violations pointed out to: UNAVAILABLE			Inspector	
THIS IS NOT AN INVOICE	To make changes to the invoice mailing address please call: 919-733-0372			
	An invoice will be mailed to:	WEST BEACH VILLA 2714 W BEACH DRIVE LONG BEACH, NC, 28		