



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
11321-7-0365
State Number
H2172

EQUIPMENT INSPECTED

State Number: H2172	Type of Unit: Hand Lift	Floor to Floor: 1 to 1
Capacity: 750	Manuf: TK	Speed: 12
Landings: 2	Installed: 02/12/2010	Rope Size: 0
Volts: 120	Complied:	Entrances: 2
OWNER	OCCUPANT	
BREMCO	BREMCO	
2375 HWY 163	2375 HWY 163	
W JEFFERSON, NC, 28654	W JEFFERSON, NC, 28654	

INSPECTION INFORMATION

Inspection Date 11/17/2011	Type Inspection Routine	Certificate Status Re-issued	Inspector 7 - Hoffman	County ASHE
-------------------------------	----------------------------	---------------------------------	--------------------------	----------------

5

VIOLATIONS

NONE

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: DALE WALTON 336-877-7666

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

BREMCO
2375 HWY 163
W JEFFERSON, NC, 28654