



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**11325-54-2953**  
State Number  
**8543**

EQUIPMENT INSPECTED

State Number: <b>8543</b>	Type of Unit: Freight	Floor to Floor: 1 to 2
Capacity: 12000	Manuf: SOUTHERN	Speed: 100
Landings: 2	Installed: 02/03/1976	Rope Size:
Volts: 480	Complied: 02/14/2000	Entrances: 1
OWNER	OCCUPANT	
PERDUE INC.	PERDUE FARMS INC	
PO BOX 1537	HWY 308 WEST	
SALISBURY, MD, 21802	LEWISTON, NC, 27849	

INSPECTION INFORMATION

Inspection Date 11/21/2011	Type Inspection Routine	Certificate Status Re-issued	Inspector 54 - Green	County BERTIE
-------------------------------	----------------------------	---------------------------------	-------------------------	------------------

8

VIOLATIONS

- 2.12.2.4.1 Install the missing interlock covers where needed.
- 8.6.4.7.1 Clean the elevator pit.
- 2.2.5.1 Put the pit lights in proper working order.
- 8.6.1.4.1[a] Properly document maintenance records
- 8.6.5.9 Relief-Valve Setting. The relief-valve adjustment shall be examined to ensure that the seal is intact. If the relief-valve seal is not intact, checks shall be conducted in accordance with 8.11.3.2.1.

Items must be corrected by: 12/21/2011

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: WILLIE MITCHELL

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

PERDUE INC.  
PO BOX 1537  
SALISBURY, MD, 21802