



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**11326-8-4993**  
State Number  
**6454**

EQUIPMENT INSPECTED

State Number: <b>6454</b>	Type of Unit: Freight	Floor to Floor: 1 to 2
Capacity: 5000	Manuf: SOUTHERN	Speed: 75
Landings: 2	Installed: 09/25/1969	Rope Size:
Volts: 240	Complied: 10/01/1969	Entrances: 2
OWNER	OCCUPANT	
ELASTIC THERAPY INC	ELASTIC THERAPY INC	
PO BOX 4068	718 INDUSTRIAL PARK AVE	
ASHEBORO, NC, 27204-4068	ASHEBORO, NC, 27204	

INSPECTION INFORMATION

Inspection Date 11/22/2011	Type Inspection Routine	Certificate Status Re-issued	Inspector 8 - Burris	County RANDOLPH
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

76

VIOLATIONS

NONE

Elevator Name: FREIGHT ELEVATOR

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: REP- HAROLD ALBRIGHT (MAINT)

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ELASTIC THERAPY INC  
PO BOX 4068  
ASHEBORO, NC, 27204-4068