

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 12013-36-3622 State Number 14573

1

	E	EQUIPMENT INSPECTED			
State Number: 14573	Type of Unit: Passenger		Floor to Floor:	Floor to Floor: 1 to 3	
Capacity: 2000	Manuf: THYSSEN KRUPP		Speed: 100	Speed: 100	
Landings: 3	Installed: 07/07/1992		Rope Size:		
Volts: 208	Complied: 07/17/1992		Entrances: 1		
OWNER	OCCUPANT				
ELON UNIVERSITY	ELON UNIV / CARLTON HALL				
803 HAGGARD AVENUE	105 E HAGGARD AVE				
ELON, NC, 27244	ELON, NC, 27244				
	INS	SPECTION INFORMATION			
Inspection Date 01/13/2012	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
None Found					
Elevator Name: CARLTON I	HALL				
Notify the Elevator Bureau in write complainace with current codes.	ting on Corrected Violations Form v	when the following corrections h	nave been made in order to bri	ng your equipment into	
/iolations pointed out to: Bob W					
	T 1 1 4 4 1				
	To make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	ELON UNIVERSITY 803 HAGGARD AVENU ELON, NC, 27244	JE		