

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 12023-36-4667 State Number 3043

1

	E	QUIPMENT INSPECTED		
State Number: 3043 Capacity: 6000 Landings: 3 Volts: 440 OWNER	Type of Unit: Passer Manuf: THYSSEN I Installed: 01/14/195' Complied: 01/14/19:	KRUPP 7	Floor to Floor: Speed: 100 Rope Size: Entrances: 1	1 to 3
AMI 2609 TUCKER ST BURLINGTON, NC, 27215		AMI 204 N GRA-HOPEE BURLINGTON, NO		
	INS	PECTION INFORMATION		
Inspection Date 01/23/2012	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
		VIOLATIONS		
None found				
complainace with current codes. Violations pointed out to: Jay 3	36-229-5554	ling address please call: 919-73	Inspector	
THIS IS NOT AN INVOICE	An invoice will be mailed to:	AMI 2609 TUCKER ST BURLINGTON, NC, 272	215	