



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
12044-36-123
State Number
12214

EQUIPMENT INSPECTED

State Number: 12214	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2100	Manuf: THYSSEN KRUPP	Speed: 100
Landings: 2	Installed: 08/20/1987	Rope Size:
Volts: 200	Complied: 08/20/1987	Entrances: 1
OWNER	OCCUPANT	
CHANDLER CONCRETE	CHANDLER CONCRETE	
PO BOX 131	1006 CHURCH ST	
BURLINGTON, NC, 27216-0131	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 02/13/2012	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

VIOLATIONS

none found

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: office 336-226-1181

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

CHANDLER CONCRETE
PO BOX 131
BURLINGTON, NC, 27216-0131