

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 12066-52-1569 State Number H1712

	EQ	UIPMENT INSPECTED		
State Number: H1712	Type of Unit: Ha	and Lift	Floor to Floor: 1 to 2	
Capacity: 750 Manuf: NATL W-O-V Landings: 2 Installed: 10/02/2006		V-O-V	Speed: 9 Rope Size: 0	
		2006		
Volts: 115	Complied: 10/02	/2006	Entrances: 1	
OWNER		OCCUPANT		
ELK PARK UNITED METHODIST ELK PARK UNITED METHODIST				
P.O. BOX 7		130 CHURCH STREET		
ELK PARK, NC, 28622		ELK PARK, NC, 28622		
	INSP	ECTION INFORMATION		
Inspection Date 03/06/2012	Type Inspection Routine	Certificate Status Re-issued	Inspector 52 - Sosebee	County AVERY
		VIOLATIONS		
n/a No violation	is found			
Notify the Elevator Bureau in writin	ag on Corrected Violations Form wh	en the following corrections have	heen made in order to bring you	r equipment into
complainace with current codes.		en the following corrections have		
Violations pointed out to: Elk Park			Inspector	
	To make changes to the invoice mailing address please call: 919-733-0372			
THIS IS NOT AN INVOICE A	ELK PARK UNITED METHODIST An invoice will be mailed to: P.O. BOX 7 FIK PARK NC 28622			