



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
12069-52-1957
State Number
H1558

EQUIPMENT INSPECTED

State Number: H1558	Type of Unit: Hand Lift	Floor to Floor: 1 to 3
Capacity: 750	Manuf: NATL W-O-V	Speed: 20
Landings: 3	Installed: 12/14/2004	Rope Size: 0
Volts: 115	Complied: 01/04/2005	Entrances: 3
OWNER	OCCUPANT	
FIRST BAPTIST CHURCH	FIRST BAPTIST CHURCH	
PO BOX 370	220 EAST CROSSNORE DRIVE	
CROSSNORE, NC, 28616	CROSSNORE, NC, 28616	

INSPECTION INFORMATION

Inspection Date 03/09/2012	Type Inspection Routine	Certificate Status Re-issued	Inspector 52 - Sosebee	County AVERY
-------------------------------	----------------------------	---------------------------------	---------------------------	-----------------

6

VIOLATIONS

n/a No violations found

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: First Baptist Church 828-733-5243

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

FIRST BAPTIST CHURCH
PO BOX 370
CROSSNORE, NC, 28616