NCDOL NCDOL N. Department of labor

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 12072-48-3085 State Number 21610

		EQUIPMENT INSPECTED		
State Number: 21610 Capacity: 2000		Type of Unit: Passenger Manuf: THYSSEN KRUPP		or: 1 to 4
Landings: 4 Installed:			Speed: 125 Rope Size:	
Volts: 208		Complied: 05/13/2003		1
OWNER	1	OCCUPANT	OCCUPANT	
CAM			ORT - BLDG. #27	
P.O. BOX 8126		2 JAN STREET	5111 BBB 51 112 /	
OCEAN ISLE BEACH, NC, 28	469	OCEAN ISLE BEACH, NC, 28469		
	I	INSPECTION INFORMATION		
Inspection Date 03/12/2012	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK 10
		VIOLATIONS		
Items must be corrected by: (Notify the Elevator Bureau in wri complainace with current codes. Violations pointed out to: UNAV	ting on Corrected Violations Form	n when the following corrections		bring your equipment into
_				
THE IS NOT AN	To make changes to the invoice mailing address please call: 919-733-0372			
THIS IS NOT AN INVOICE	An invoice will be mailed to:	CAM P.O. BOX 8126 OCEAN ISLE BEACH,	NC, 28469	