

Report Number 12081-36-1199 State Number 25796

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-807-2770

EQUIPMENT INSPECTED

State Number: 25796	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2500	Manuf: OTIS	Speed: 100
Landings: 2	Installed: 12/23/2008	Rope Size:
Volts: 208	Complied:	Entrances: 1
OWNER		OCCUPANT
CHAD PORTERFIELD		WOODBURY PARK
2004A ANTHONY ROAD		2929 CROUSE LANE
BURLINGTON, NC, 27215		BURLINGTON, NC, 27215

INSPECTION INFORMATION

Inspection Date 03/21/2012	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

VIOLATIONS

none found at time of inspection

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: MIKE 336-516-4761

Inspector _____

THIS IS NOT AN INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

CHAD PORTERFIELD
2004A ANTHONY ROAD
BURLINGTON, NC, 27215