



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
12083-36-2842
State Number
15427

EQUIPMENT INSPECTED

| | | |
|-------------------------------------|--------------------------|------------------------|
| State Number: 15427 | Type of Unit: Passenger | Floor to Floor: 1 to 2 |
| Capacity: 2100 | Manuf: THYSSEN KRUPP | Speed: 100 |
| Landings: 2 | Installed: 10/11/1994 | Rope Size: |
| Volts: 208 | Complied: 10/14/1994 | Entrances: 1 |
| OWNER | OCCUPANT | |
| ALAMANCE - BURLINGTON SCHOOL SYSTEM | TURRENTINE MIDDLE SCHOOL | |
| 1712 VAUGHN RD | 1710 EDGEWOOD AVE | |
| BURLINGTON, NC, 27217 | BURLINGTON, NC, 27215 | |

INSPECTION INFORMATION

| | | | | |
|-------------------------------|----------------------------|---------------------------------|---------------------------|--------------------|
| Inspection Date 03/23/2012 | Type Inspection Routine | Certificate Status Re-issued | Inspector 36 - Kirkman | County ALAMANCE |
|-------------------------------|----------------------------|---------------------------------|---------------------------|--------------------|

VIOLATIONS

| | |
|-----------|--------------------------------------|
| 8.6.4.7.1 | Clean the elevator pit. |
| 8.6.10.1 | Update the monthly fire service log. |

Items must be corrected by: 04/22/2012

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: carolyn christopher 336-570-6150

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ALAMANCE - BURLINGTON SCHOOL SYSTEM
1712 VAUGHN RD
BURLINGTON, NC, 27217