

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 12086-36-2227 State Number 5446

1

EQUIPMENT INSPECTED				
State Number: 5446	Type of Unit: Fi	reight	Floor to Floor: 1 to	2
Capacity: 2000	Manuf: SOUTH	ERN	Speed: 50	
Landings: 2	Installed: 10/24/	1967	Rope Size:	
Volts: 220	Complied: 11/10	0/1965	Entrances: 1	
OWNER		OCCUPANT		
WRIGHTENBERRY MILLS INC	WRIGHTENBERRY MILLS INC			
910 CLEVELAND		910 CLEVELAND		
BURLINGTON, NC, 27217		BURLINGTON, NC, 27217		
	INS	SPECTION INFORMATION		
Inspection Date 03/26/2012	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
		VIOLATIONS		
NONE FOUND				
NONE FOUND				
otify the Elevator Bureau in writing mplainace with current codes.	g on Corrected Violations Form v	when the following corrections h	nave been made in order to bri	ng your equipment into
iolations pointed out to: JOEY W				
	make changes to the invoice mailing address please call: 919-733-0372			
THIS IS NOT AN INVOICE A	n invoice will be mailed to:	WRIGHTENBERRY MI 910 CLEVELAND BURLINGTON, NC, 272		