



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
12102-36-2252
State Number
21988

EQUIPMENT INSPECTED

State Number: 21988	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2100	Manuf: THYSSEN KRUPP	Speed: 80
Landings: 2	Installed: 10/16/2003	Rope Size: 0
Volts: 208	Complied: 10/16/2003	Entrances: 1

OWNER

MEBANE POLICE STATION
116 W CENTER STREET
MEBANE, NC, 27302

OCCUPANT

MEBANE POLICE STATION
116 W CENTER STREET
MEBANE, NC, 27302

INSPECTION INFORMATION

Inspection Date 04/11/2012	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

VIOLATIONS

None found

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: TERRANCE CALDWELL 919-563-9031

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

MEBANE POLICE STATION
116 W CENTER STREET
MEBANE, NC, 27302