

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 12108-30-4061 State Number 15586

	E	QUIPMENT INSPECTED			
State Number: 15586	Type of Unit: Passenger		Floor to Floor:	Floor to Floor: 1 to 2	
Capacity: 2500	Manuf: THYSSEN KRUPP		Speed: 100	Speed: 100	
Landings: 2	Installed: 03/07/1995		Rope Size:	Rope Size:	
Volts: 480	Complied: 02/21/2002		Entrances: 1		
OWNER	OCCUPANT				
KERNODLE CLINIC		KERNODLE CLINIC #1			
1234 HUFFMAN MILL RD		1234 HUFFMAN MILL RD			
BURLINGTON, NC, 27215		BURLINGTON, NC, 27215			
	INS	PECTION INFORMATION			
Inspection Date 04/17/2012	Type Inspection Routine	Certificate Status Re-issued	Inspector 30 - Wall	County ALAMANCE	
		VIOLATIONS			
None found					
110110 10 0110					
otify the Elevator Bureau in wr	iting on Corrected Violations Form w	hen the following corrections have	been made in order to br	ing your equipment into	
Violations pointed out to: BILL 336-538-2370					
	To make changes to the invoice ma				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	KERNODLE CLINIC 1234 HUFFMAN MILL RD BURLINGTON NC 27215			