NCDOL NCDOL

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 12117-48-4329 State Number 22892

		EQUIPMENT INSPECTED			
State Number: 22892 Type of Unit: Pas		Passenger	Floor to Floor: 1 to 3		
Capacity: 2100 Manuf: OTIS			Speed: 100		
Landings: 3 Installed: 03/02/200. Volts: 240 Complied: 03/02/20		2/2005	1		
		02/2005			
OWNER		OCC	OCCUPANT		
COMMUNITY ASSOCIATION MGMT. P.O. BOX 8126 OCEAN ISLE BEACH, NC, 28469		VILI	AS ON OSPREY RIDGE		
		182 (182 CLUBHOUSE RD. SUNSET BEACH, NC, 28468		
		SUN			
	IN	SPECTION INFORMATION			
Inspection Date 04/25/2012	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK 1	
		VIOLATIONS			
complainace with current codes Violations pointed out to: UNA	vriting on Corrected Violations Form vs.	-	Inspector		
THIS IS NOT AN INVOICE	An invoice will be mailed to:	To make changes to the invoice mailing address please call: 919-733-0372 COMMUNITY ASSOCIATION MGMT. An invoice will be mailed to: P.O. BOX 8126 OCEAN ISLE BEACH, NC, 28469			