



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
12118-36-131
State Number
H225

EQUIPMENT INSPECTED

State Number: H225	Type of Unit: Hand Lift	Floor to Floor: 1 to 2
Capacity: 500	Manuf: PORCHLIFT	Speed: 10
Landings: 2	Installed: 06/16/1987	Rope Size:
Volts: 110	Complied: 06/16/1987	Entrances: 2
OWNER	OCCUPANT	
NORTHSIDE CHURCH OF CHRIST	NORTHSIDE CHURCH OF CHRIST	
PASTOR ROBERT BREWINGTON	820 HARRIS STREET	
BURLINGTON, NC, 27216	BURLINGTON, NC, 27216	

INSPECTION INFORMATION

Inspection Date 04/27/2012	Type Inspection Not Inspected	Certificate Status Not Issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------------	----------------------------------	---------------------------	--------------------

1

VIOLATIONS

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: n/a

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

NORTHSIDE CHURCH OF CHRIST
PASTOR ROBERT BREWINGTON
BURLINGTON, NC, 27216