

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 12128-36-3498 State Number 5904

1

		EQUIPMENT INSPECTED			
State Number: <b>5904</b> Capacity: 3000 Landings: 2	Type of Unit: Manuf: WEST Installed: 08/0	BROOK 9/1967	OK Speed: 35		
Volts: 550	Complied: 09/19/1994		Entrances: 1		
OWNER	OCCUPANT				
KINGSDOWN INC	KINGSDOWN INC				
126 W HOLT ST		126 W HOLT ST			
MEBANE, NC, 27302		MEBANE, NC, 27	7302		
	Γ.	NSPECTION INFORMATION			
Inspection Date 05/07/2012	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
Items must be corrected b	y: 06/06/2012				
Notify the Elevator Bureau in complainace with current code	writing on Corrected Violations Fornes.	n when the following corrections h	nave been made in order to bri	ng your equipment into	
Violations pointed out to: TIM					
THIS IS NOT AN INVOICE		nailing address please call: 919-73 KINGSDOWN INC 126 W HOLT ST MEBANE, NC, 27302			