



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

### INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**12138-36-0062**  
State Number  
**8209**

#### EQUIPMENT INSPECTED

State Number: <b>8209</b>	Type of Unit: Passenger	Floor to Floor: 1 to 3
Capacity: 2000	Manuf: OTIS	Speed: 100
Landings: 3	Installed: 12/16/1975	Rope Size:
Volts: 208	Complied: 12/09/2002	Entrances: 1
OWNER	OCCUPANT	
ALAMANCE COMMUNITY COLLEGE	ALAMANCE COMMUNITY COLLEGE	
1247 JIMMIE KERR ROAD	1247 JIMMIE-KERR ROAD	
GRAHAM, NC, 27253	GRAHAM, NC, 27253	

#### INSPECTION INFORMATION

Inspection Date 05/17/2012	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

#### VIOLATIONS

2.27.1.1.2 Put the in car emergency telephone in proper working order.NEED PROPER IDENTIFICATION FOR LOCATION AND CALL BACK NUMBER  
WHEN CALLINNG BACK INTO ELEVATOR!

Items must be corrected by: 06/16/2012

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into  
complainace with current codes.

Violations pointed out to: eric 336-538-2002

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ALAMANCE COMMUNITY COLLEGE  
1247 JIMMIE KERR ROAD  
GRAHAM, NC, 27253