



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
12142-36-4165
State Number
6293

EQUIPMENT INSPECTED

State Number: 6293	Type of Unit: Freight	Floor to Floor: B to 1
Capacity: 4000	Manuf: SOUTHERN	Speed: 100
Landings: 2	Installed: 05/20/1969	Rope Size:
Volts: 240	Complied: 05/20/1969	Entrances: 2
OWNER	OCCUPANT	
STADLER COUNTRY HAMS INC	STADLER COUNTRY HAMS INC	
2921 NC 100	2921 NC 100	
ELON COLLEGE, NC, 27244	ELON COLLEGE, NC, 27244	

INSPECTION INFORMATION

Inspection Date 05/21/2012	Type Inspection Not Inspected	Certificate Status Not Issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------------	----------------------------------	---------------------------	--------------------

1

VIOLATIONS

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: n/a

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

STADLER COUNTRY HAMS INC
2921 NC 100
ELON COLLEGE, NC, 27244