



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
12143-36-1231
State Number
22475

EQUIPMENT INSPECTED

| | | |
|------------------------------------|-------------------------|------------------------|
| State Number: 22475 | Type of Unit: Passenger | Floor to Floor: 1 to 3 |
| Capacity: 2500 | Manuf: SCHINDLER | Speed: 125 |
| Landings: 3 | Installed: 05/25/2004 | Rope Size: 0 |
| Volts: 460 | Complied: 05/25/2004 | Entrances: 1 |
| OWNER | | OCCUPANT |
| AKG | | AKG |
| 7315 OAK WOOD ST EXT: COLLIN BROWN | | 7315 OAK WOOD ST EXT |
| MEBANE, NC, 27302 | | MEBANE, NC, 27302 |

INSPECTION INFORMATION

| | | | | |
|-------------------------------|----------------------------|---------------------------------|---------------------------|--------------------|
| Inspection Date 05/22/2012 | Type Inspection Routine | Certificate Status Re-issued | Inspector 36 - Kirkman | County ALAMANCE |
|-------------------------------|----------------------------|---------------------------------|---------------------------|--------------------|

1

VIOLATIONS

None Found

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: TAMMY ANDREWS 919-563-4286

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

AKG
7315 OAK WOOD ST EXT: COLLIN BROWN
MEBANE, NC, 27302