



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
12144-36-533
State Number
H1544

EQUIPMENT INSPECTED

State Number: **H1544**

Capacity: 550

Landings: 4

Volts: 220

Type of Unit: Hand Lift

Manuf: GARAVENTA

Installed: 10/11/2004

Complied: 10/11/2004

Floor to Floor: 1 to 4

Speed: 20

Rope Size:

Entrances: 2

OWNER

ALAMANCE BURLINGTON SCHOOL

1712 VAUGHN ROAD

BURLINGTON, NC, 27217

OCCUPANT

GROVE PARK ELEMENTARY

141 TRAIL ONE

BURLINGTON, NC, 27215

INSPECTION INFORMATION

Inspection Date
05/23/2012

Type Inspection
Routine

Certificate Status
Re-issued

Inspector
36 - Kirkman

County
ALAMANCE

1

VIOLATIONS

NONE FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into
complainance with current codes.

Violations pointed out to: office (336) 883-6434

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ALAMANCE BURLINGTON SCHOOL
1712 VAUGHN ROAD
BURLINGTON, NC, 27217