N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
12160-16-5085
State Number
N7.19

EQUIPMENT INSPECTED

State Number: **N7.19**
Capacity: 2000
Landings: 2
Volts: 220

Type of Unit: Freight
Manuf: WESTBROOK
Installed: 08/29/1979
Complied: 08/29/1979

Floor to Floor: 1 to 2
Speed: 50
Rope Size: 5/8
Entrances: 2

OWNER
MAOLA ICE CREAM COMPANY
PO BOX 759
WASHINGTON, NC, 27889

OCCUPANT
UNOCCUPIED BUILDING
115 EAST WATER ST
WASHINGTON, NC, 27889

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County
06/08/2012	Routine	Re-issued	16 - Moore	BEAUFORT

7

VIOLATIONS

n/a No violations found

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: Doug For Maola

Inspector _____

THIS IS NOT AN INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:
MAOLA ICE CREAM COMPANY
PO BOX 759
WASHINGTON, NC, 27889