

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 12163-52-1981 State Number 23277

6

EQUIPMENT INSPECTED						
State Number: 23277		Type of Unit: Passenger		Floor to Floor: 1 to 2		
Capacity: 2100		Manuf: THYSSEN KRUPP		Speed: 80		
Landings: 2		Installed: 07/28/2005		Rope Size: 0		
Volts: 208		Complied: 02/16/2006		Entrances: 1		
OWNER			OCCUPANT			
ELK RIVER COUNTRY CLUB			ELK RIVER CLUBHOUSE			
1000 CLUBHOUSE DRIVE		235 CLUB HOUSE DRIVE				
BANNER ELK, NC, 28604		BANNER ELK, NC, 28604				
		INSPE	ECTION INFORMATION			
Inspection Date 06/11/2012		Type Inspection Routine	Certificate Status Re-issued	Inspector 52 - Sosebee	County AVERY	
			VIOLATIONS			
8.6.4.7.4	Take steps to eliminate the accumulation of water on the pit floor and remove same.					
2.27.1.1.2	Put the in car emergency telephone in proper working order.					
8.6.5.16.5	Perform the 5 year full load test on the overspeed valve.					
3.6.1.7.2	Provide the proper metal tag to the controller for all periodic tests.					
8.6	Perform the annual inspection on the machine room fire extinguisher.					
Items mus	st be corrected by: 07/1	1/2012		Elevator Name: # 2		
	vator Bureau in writing	g on Corrected Violations Form who	en the following corrections have b	een made in order to bring your	equipment into	

To make changes to the invoice mailing address please call: 919-733-0372

THIS IS NOT AN INVOICE

An invoice will be mailed to:

Violations pointed out to: Elk River Country Club 828-898-9773

ELK RIVER COUNTRY CLUB 1000 CLUBHOUSE DRIVE BANNER ELK, NC, 28604 Inspector \_\_\_\_\_