



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
12172-36-354
State Number
15764

EQUIPMENT INSPECTED

State Number: 15764	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2100	Manuf: THYSSEN KRUPP	Speed: 125
Landings: 3	Installed: 05/04/1995	Rope Size:
Volts: 208	Complied: 05/04/1995	Entrances: 1

OWNER

FIRST BAPTIST CHURCH
301 S THIRD STREET
MEBANE, NC, 27302

OCCUPANT

FIRST BAPTIST CHURCH
301 S THIRD STREET
MEBANE, NC, 27302

INSPECTION INFORMATION

Inspection Date 06/20/2012	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

VIOLATIONS

8.6.1.7.2 A metal tag with the applicable code requirement(s) and date(s) performed, and the name of the person or firm performing the test, shall be installed to be readily visible and securely attached to the controller of each unit for all periodic tests.

Items must be corrected by: 07/20/2012

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Rhonda 919-563 5498

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

FIRST BAPTIST CHURCH
301 S THIRD STREET
MEBANE, NC, 27302