



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

### INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**12172-36-5135**  
State Number  
**20130**

#### EQUIPMENT INSPECTED

State Number: <b>20130</b>	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2100	Manuf: MINNESOTA	Speed: 100
Landings: 2	Installed: 07/10/2001	Rope Size:
Volts: 480	Complied: 08/08/2001	Entrances: 2
OWNER	OCCUPANT	
ALAMANCE BURLINGTON SCH SYS	WOODLAWN MIDDLE SCHOOL	
1712 VAUGHN RD	3970 MEBANE ROGERS RD	
BURLINGTON, NC, 27215	MEBANE, NC, 27302	

#### INSPECTION INFORMATION

Inspection Date 06/20/2012	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

#### VIOLATIONS

- 2.27.1.1.2 Put the in car emergency telephone in proper working order.
- 8.6.1.7.2 A metal tag with the applicable code requirement(s) and date(s) performed, and the name of the person or firm performing the test, shall be installed to be readily visible and securely attached to the controller of each unit for all periodic tests.
- 8.6 TAKE STEPS TO REPAIR OR REPLACE BROKEN VENT DUE TO SHARP EDGES.
- 8.6 PROVIDE THE MISSING DROP CEILING TILES IN ELEVATOR.

Items must be corrected by: 07/20/2012

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: CINDY HOPKINS 919-563-3222

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ALAMANCE BURLINGTON SCH SYS  
1712 VAUGHN RD  
BURLINGTON, NC, 27215