

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 12172-48-1758 State Number H1749

		EQUIPMENT INSPECTED		
State Number: H1749	Type of Unit	: Hand Lift	Lift Floor to Floor: 1 to 2	
Capacity: 750		Manuf: GARAVENTA Installed: 09/07/2006 Complied: 09/07/2006		
Landings: 2	Installed: 09			
Volts: 120	Complied: 0			Rope Size: 0 Entrances: 1
OWNER	OCCUPANT LE BEACH RESORT AT OIB			
OCEAN ISLE BEACH				
103 W 1ST STREET				
OCEAN ISLE, NC, 28469		OCEAN ISLE, N		
	Γ.	NSPECTION INFORMATION		
Inspection Date 06/20/2012	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK
		VIOLATIONS		
	writing on Corrected Violations Forn	n when the following corrections	have been made in order to	bring your equipment into
complainace with current code	S.	C		
Violations pointed out to: WA	NDA TATE			
THIS IS NOT AN INVOICE	To make changes to the invoice of An invoice will be mailed to:	nailing address please call: 919-7 OCEAN ISLE BEACH 103 W 1ST STREET OCEAN ISLE, NC, 284		