NCDOL NCDOL N. Department of labor

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 12172-48-5228 State Number H1874

	EQ	UIPMENT INSPECTED			
State Number: H1874	Type of Unit: Ha	and Lift	1 Lift Floor to Floor: 1 to 2		
Capacity: 750	Manuf: GARAVENTA		Speed: 17		
Landings: 2	Installed: 04/10/2008		Rope Size:		
Volts: 120 Complied: 04/10)/2008	Entrances: 1		
OWNER	ACH MANAGEMENT PENINSULA CLUBHOUSE				
BEACH MANAGEMENT					
PO BOX 6569					
OCEAN ISLE BEACH, NC, 2846	9	OCEAN ISLE BEACH, NC, 28469			
	INSP	ECTION INFORMATION			
Inspection Date 06/20/2012	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	
		VIOLATIONS			
Items must be corrected by: 07/		en the following corrections	have been made in order to l	oring your equipment into	
complainace with current codes. Violations pointed out to: WANDA	TATE		Inspector		
T	o make changes to the invoice maili				
THIS IS NOT AN INVOICE	n invoice will be mailed to:	BEACH MANAGEMEN PO BOX 6569 OCEAN ISLE BEACH.			