NCDOL NCDOL NA Department of later

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 12184-48-1867 State Number 20861

| | | | EQUIPMENT INSPECTED | | | |
|--|--------------|----------------------------|---------------------------------|--------------------------|---------------------|----|
| State Number: 208 | 861 | Type of Unit: Passenger | | Floor to Floor: 1 to 3 | | |
| Capacity: 3500 | | Manuf: OTIS | | Speed: 150 | | |
| Landings: 3 | | Installed: 10/16/2002 | | Rope Size: 0 | | |
| Volts: 208 | | Complied: 10/16/2002 | | Entrances: 1 | | |
| OWNER | | OCCUPANT | | | | |
| SEA TRAIL CORPORATION | | SEA TRAIL CHAMPIONS #36 | | | | |
| 279 CLUBHOUS | SE ROAD | 139 AVIAN DRIVE | | | | |
| SUNSET BEACH | H, NC, 28468 | SUNSET BEACH, NC, 28468 | | | | |
| | | | INSPECTION INFORMATION | | | |
| Inspection Date 07/02/2012 | | Type Inspection Routine | Certificate Status Re-issued | Inspector 48 - Martin | County BRUNSWICK | 10 |
| | | | VIOLATIONS | | | |
| 2.27.1.1.2 Put the in car emergency telephone in proper working order. 8.6.4.8.2 Remove all materials from machine room (machinery space) not pertaining to the maintenance or operation of the elevator(s). 8.6.4.13.1[k] Properly maintain door closers, where required. MOTOR ROOM DOOR | | | | | | |

Items must be corrected by: 08/01/2012

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: UNAVAILABLE Inspector _____

To make changes to the invoice mailing address please call: 919-733-0372

THIS IS NOT AN INVOICE

An invoice will be mailed to:

SEA TRAIL CORPORATION 279 CLUBHOUSE ROAD SUNSET BEACH, NC, 28468