

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-807-2770

Report Number 12185-8-3888 State Number 24815
--

EQUIPMENT INSPECTED

State Number: 24815	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 4000	Manuf: ABELL	Speed: 75
Landings: 2	Installed: 01/05/2012	Rope Size:
Volts: 480	Complied:	Entrances: 1
OWNER	OCCUPANT	
LANESBORO CORRECTIONAL	LANESBORO CORRECTIONAL INSTITUTE	
P O BOX 280	552 PRISON CAMP ROAD	
POLKTON, NC, 28135	POLKTON, NC, 28135	

INSPECTION INFORMATION

Inspection Date 07/03/2012	Type Inspection New	Certificate Status Not Issued	Inspector 8 - Burris	County ANSON
-------------------------------	------------------------	----------------------------------	-------------------------	-----------------

4

VIOLATIONS

A17.1 ELEVATOR NOT READY FOR INSPECTION CONTACT NCDOL WHEN READY FOR INSPECTION
CERTIFICATE NOT ISSUED

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: DAVID DOSS

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

LANESBORO CORRECTIONAL
P O BOX 280
POLKTON, NC, 28135