

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
www.nclabor.com/elevator.htm  
919-807-2770

Report Number <b>12185-8-3888</b> State Number <b>24815</b>
--

EQUIPMENT INSPECTED

State Number: <b>24815</b>	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 4000	Manuf: ABELL	Speed: 75
Landings: 2	Installed: 01/05/2012	Rope Size:
Volts: 480	Complied:	Entrances: 1
OWNER	OCCUPANT	
LANESBORO CORRECTIONAL	LANESBORO CORRECTIONAL INSTITUTE	
P O BOX 280	552 PRISON CAMP ROAD	
POLKTON, NC, 28135	POLKTON, NC, 28135	

INSPECTION INFORMATION

Inspection Date 07/03/2012	Type Inspection New	Certificate Status Not Issued	Inspector 8 - Burris	County ANSON
-------------------------------	------------------------	----------------------------------	-------------------------	-----------------

4

VIOLATIONS

A17.1 ELEVATOR NOT READY FOR INSPECTION CONTACT NCDOL WHEN READY FOR INSPECTION  
CERTIFICATE NOT ISSUED

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: DAVID DOSS

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372  
An invoice will be mailed to: LANESBORO CORRECTIONAL  
P O BOX 280  
POLKTON, NC, 28135