

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 12200-36-4869 State Number H1261

1

	1	EQUIPMENT INSPECTED			
State Number: H1261	Type of Unit: Hand Lift		Floor to Floor: 1	Floor to Floor: 1 to 2	
Capacity: 750	Manuf: GARAVENTA		Speed: 11		
Landings: 2	Installed: 07/12/2002		Rope Size: .	_	
Volts: 220	Complied: 07/12/2002		Entrances: 2		
OWNER	OCCUPANT				
ALAMANCE CO SCHOOLS	ALTAMA	ALTAMAHAW/OSSIPPEE ELEMENTARY SCHOOL			
1712 VAUGHAN RD	2832 N HWY 87				
BURLINGTON, NC, 27217	ELON, NO	C, 27244			
	IN	SPECTION INFORMATION			
Inspection Date 07/18/2012	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
none found					
Notify the Elevator Bureau in write complainace with current codes.	ing on Corrected Violations Form	when the following corrections h	nave been made in order to bri	ing your equipment into	
Violations pointed out to: office r	eginald davis 336-570-6195		Inspector		
	o make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	ALAMANCE CO SCHO 1712 VAUGHAN RD BURLINGTON, NC, 272			